COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KX19AZA

Isuzu D-Max 2.5TD

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	ISDM25 PDTM4 L

Details

Location	Doncaster	**GVW**	3500kg	**Gearbox**	MANUAL
Reg. date	14/06/2019	**Colour**	WHITE	**Gears**	6
Year	2019	**VIN**	MPATFS87JJT010090	**Axle Combi**	4x4
Mileage	100,293 Miles Warranted	**Body Style**	Access Platform		
Fuel Type	DIESEL	**MOT Due**	18/02/2027		

*WARNING LIGHTS ON DASH *CPL PALFINGER P130A PLATFORM (YEAR 2019), E/MIRRORS

Tyres

NSF	
NSR	Punctured
OSF	
OSR	Punctured
Spare	

Features

- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos




























LOLER SERVICE RECORD
CPL
WARNING

CPL
WWW.CPL-LTD.COM


CPL


Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Dented
With Paint Damage



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wing nsf
Dented
Over 30mm



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: A Post ns
Dented
With Paint Damage



9: Door nsf
Chipped
Multiple Chips



10: B Post ns
Dented
With Paint Damage



11: Other
N/A
N/A



12: Other
N/A
N/A



13: B Post os
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



16: Door osf
Dented
With Paint Damage



17: Wing osf
Dented
With Paint Damage



18: Wing osf
Dented
With Paint Damage



19: Seat Base Cover osf
Soiled
Heavy



20: Seat Base Cover nsf
Soiled
Heavy



21: Fascia Panel
Scuffed
Over 25mm



22: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault